

## **TYPHOON DRILL 2020**

**July - 11 - 2020** 














9:00AM E&E teams went to the designated assembly points – E&E warehouse Taipa, Macau tower and NAPE









- Around 9.30 4 of the prioritized CDIP in Macau, 2 in Taipa and 1 in Coloane were open to simulate a fault.
- Once these CDIPs were opened, the new CEM software sent a fault information by e-mail.
- This fault e-mail was detected by E&E software and generate a Service order for the fast CDIP intervention teams.
- At same time patrollers went to other CDIPs of the prioritized list (3 CDIP in Macau, 1 in Taipa and 1 in Coloane)
- A list of 3 poles of each CDIP were opened by the patrollers to turn the MCB off simulating a fault. This fault was registered on the E&E software generating a service order.
- With the combination of the two pieces of software, the repair teams were provided with fast and efficient information.

Poles Database							Crisis Repo	rt	Í.	Se	
Cable Database											h:
ole Search	CDIPIP *	Address	Pole Type	Lantern (	Power	Failure Code	Failure Detected by	Zone	Failure Date	Remark	Status
coments	169	獲馬街&共星有大馬器	NA	0	NA	Faulti	PoL	1A	2020-07-11	Door open	1 - Done
0.000	191	河邊附位	N/A	0	NA	Fault	PoL	1	2020-07-11	Door open	1 - Done
	21	鸭满可造街	N/A	0	NA	Damaged Box / 拆好的盒子	helder	4	2020-07-11	Arriving at the place the door was open , it was closed now	1 - Done
	240	友谊大师描述策方置这行事关格	NA.	.0	NA	Fault	PoL	1A	2020-07-11		1 - Don
	240A05	并选仙大馬路	P12M LED	1	174	Phase off / 拉路求规型	jeftey	1A	2020-07-11		1 - Don
	240806	高速仙大馬路	P12M LED	1	174	Phase off / 批版求批型	joffrey	1A	2020-07-11		1 - Done
	240B10	拼進仙大馬筋	P12M LED	1	174	Phase off / 班班式就型	joffrey	1A	2020-07-11		1 - Don
	242	青州大馬路,青州新路(近偏矮中心)	NA	0	NA	Faulti	PoL	4	2020-07-11		1 - Don
	242C11	28/84/8	P10M	1	120	Phase off / HENG INTRO	ryan	1	2020-07-11		1 - Don
	242001	沙梨园北街	P10M	1	120	Phase off / 短線式測量	ryan	3	2020-07-11		1 - Don
	CDIP/IP	Address	Pole Type	Lantern	Power	Failure Code	Failure Detected by	Zone	Failure Date	Remark	Status
	Showing 1 to	10 of 29 entries								р	evious

## ▼ 【CEM】2台活鉄设备事件通知 From: 【CEM】照明系統管理员 Date: 07/11/2020 (10 02 06 AM CST) To: database@empresaelectrica.com.mo 1.路灯箱【CDIP0902】当前运行状态为[告警],异常信息: 门磁状态变化 当前时间段内收到1条门1磁状态变化事件记录: 告警出現时间: 07-11 09-52:44 2.路灯箱【CDIP0728】当前运行状态为估等),异常信息: 门磁状态变化 当前时间段内收到1条门1磁状态变化]事件记录: 告警出現时间: 07-11 09:56:54 ▼ 【CEM】4台系联设备事件通知 From: 【CEM】明系统管理员 Date: 07/11/2020 (10 22 12 22 M CST) To: database@empresaelectrica.com.mo

• Text (1 KB) 👤 🚔

当前时间段内收到3条[门磁状态变化]事件记录, 告警出現时间,07-11 10:19:36 告警消失时间,07-11 10:17:01

音響視及明旬, 07-11 10.14:56 告警出現时间, 07-11 10.14:56 2路打箱【CDIP0728】当前运行状态为[正常] 当前时间段内收到3条[门磁状态变化]事件记录, 告警消失时间, 07-11 10:20:42

当前时间段内收到2条门磁状态变化/事件记录。 告警消失时间。77-11 10:19:10 4整出界时间。77-11 10:19:06 4路灯霜【CDIP0902】当前运行状态为[正常] 当前时间段内收到1条[门磁状态变化]事件记录。 告警消失时间。07-11 10:17:50

告警出現 时间: 07-11 10:20:37 告警消失 时间: 07-11 10:19:49

1.路灯箱【CDIP0169】当前运行状态为[故障],异常信息: 开灯时出线无电流 门磁状态变化

3.路灯箱【CDIP0247】当前运行状态为[故障],异常信息:开灯时出线无电流





Once the teams received the faults, they immediately went to the fault locations.











The drill produced the following relevant conclusions:

- The interconnection between the new CDIP fault detection and E&E software is trustable and efficient;
- Response time of the CDIP fast intervention and repair teams is quick;
- Patrolling teams are fast in covering the prioritized CDIP areas of all Macau, Taipa and Coloane;

In the event of a typhoon everything will be ready to respond quickly and effectively.



